SECTION 8

POWER TAKE-OFF - TORQMATIC CONVERTER

For service and overhaul procedures covering the Power Take-Offs, refer to the *Power Take-Offs Manual, Form 6SE456*. Refer to this manual for the Rockford Front Disconnect Mechanical Clutch adjustment used with the Allison 800-900 Series Torque Converter.

For service and overhaul information covering the Torqmatic Converter, refer to the manufacturer's service manuals:

Allison 500 Series Torqmatic Converter Service Manual – Form SA 1058. Allison 800–900 Series Torqmatic Converter Service Manual – Form SA 1054.

Refer to SA 1054 for the Industrial Clutch Company Front Disconnect Mechanical Clutch adjustment.